

Water Testing Results - Elmira Elementary

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Health Room Faucet	20840100-001NS	11/30/2022	2.78
Health Room Drinking Fountain	20840100-002DW	11/30/2022	ND
Health Room Restroom Sink	20840100-003BF	11/30/2022	4.38
Front Office Restroom Sink	20840100-004BF	11/30/2022	ND
Staff Lounge Sink	20840100-005SF	11/30/2022	ND
Front Atrium Drinking Fountain - Left	20840100-006DW	11/30/2022	ND
Front Atrium Drinking Fountain - Right	20840100-007DW	11/30/2022	4.05
Front Atrium Water Bottle Station	20840100-008WB	11/30/2022	ND
Grades 4-5 Restroom Sink - Left	20840100-009BF	11/30/2022	ND
Grades 4-5 Restroom Sink - Middle	20840100-010BF	11/30/2022	ND
Grades 4-5 Restroom Sink - Right	20840100-011BF	11/30/2022	ND
Grades 4-5 Staff Restroom Sink	20840100-012BF	11/30/2022	ND
Room 1 - Classroom Sink	20840100-013CF	11/30/2022	2.16
Room 1 - Classroom Drinking Fountain	20840100-014DW	11/30/2022	ND
Room 2 - Classroom Sink	20840100-015CF	11/30/2022	2.35
Room 2 - Classroom Drinking Fountain	20840100-016DW	11/30/2022	ND
Room 3 - Classroom Sink	20840100-017CF	11/30/2022	2.15
Room 3 - Classroom Drinking Fountain	20840100-018DW	11/30/2022	ND
Room 4 - Classroom Sink	20840100-019CF	11/30/2022	2.19
Room 4 - Classroom Drinking Fountain	20840100-020DW	11/30/2022	2.06
Grades 2-3 Restroom Sink - Left	20840100-021BF	11/30/2022	ND
Grades 2-3 Restroom Sink - Middle	20840100-022BF	11/30/2022	ND
Grades 2-3 Restroom Sink - Right	20840100-023BF	11/30/2022	ND
Grades 2-3 Staff Restroom Sink	20840100-024BF	11/30/2022	ND
Room 5 - Classroom Sink	20840100-025CF	11/30/2022	ND
Room 5 - Classroom Drinking Fountain	20840100-026DW	11/30/2022	ND
Room 6 - Classroom Sink	20840100-027CF	11/30/2022	ND
Room 6 - Classroom Drinking Fountain	20840100-028DW	11/30/2022	2
Room 7 - Classroom Sink	20840100-029CF	11/30/2022	ND

Room 7 - Classroom Drinking Fountain	20840100-030DW	11/30/2022	ND
Room 8 - Classroom Sink	20840100-031CF	11/30/2022	2.03
Room 8 - Classroom Drinking Fountain	20840100-032DW	11/30/2022	ND
Grades K-1 Restroom Sink - Left	20840100-033BF	11/30/2022	ND
Grades K-1 Restroom Sink - Middle	20840100-034BF	11/30/2022	ND
Grades K-1 Restroom Sink -Right	20840100-035BF	11/30/2022	ND
Grades K-1 Staff Restroom Sink	20840100-036BF	11/30/2022	ND
Room 9 - Classroom Sink	20840100-037CF	11/30/2022	2.92
Room 9 - Classroom Drinking Fountain	20840100-038DW	11/30/2022	ND
Room 10 - Classroom Sink	20840100-039CF	11/30/2022	ND
Room 10 - Classroom Drinking Fountain	20840100-040DW	11/30/2022	2.09
Room 11 - Classroom Sink	20840100-041CF	11/30/2022	4
Room 11 - Classroom Drinking Fountain	20840100-042DW	---	No Sample
Room 12 - Classroom Sink	20840100-043CF	11/30/2022	ND
Room 12 - Classroom Drinking Fountain	20840100-044DW	11/30/2022	ND
Resource Hallway Restroom Sink	20840100-045BF	11/30/2022	ND
Room 13 - Classroom Sink	20840100-046CF	11/30/2022	2.25
Room 13 - Classroom Drinking Fountain	20840100-047DW	11/30/2022	ND
Room 14 - Classroom Sink	20840100-048CF	11/30/2022	ND
Room 14 - Classroom Drinking Fountain	20840100-049DW	11/30/2022	ND
Room 15 - Classroom Sink	20840100-050CF	11/30/2022	3.39
Room 15 - Classroom Drinking Fountain	20840100-051DW	11/30/2022	ND
Main Hallway Restroom Sink - Women - Left	20840100-052BF	11/30/2022	ND
Main Hallway Restroom Sink - Women - Middle	20840100-053BF	11/30/2022	ND
Main Hallway Restroom Sink - Women - Right	20840100-054BF	11/30/2022	ND
Main Hallway Restroom Sink - Men - Left	20840100-055BF	11/30/2022	ND
Main Hallway Restroom Sink - Men - Middle	20840100-056BF	11/30/2022	ND
Main Hallway Restroom Sink - Men - Right	20840100-057BF	11/30/2022	ND
Cafeteria Restroom Sink	20840100-058BF	11/30/2022	ND
Cafeteria Drinking Fountain - Left	20840100-059DW	11/30/2022	ND
Cafeteria Drinking Fountain - Right	20840100-060DW	11/30/2022	ND
Kitchen - Handwash Sink Nearest Main Door	20840100-061KF	11/30/2022	2.17
Kitchen - Handwash Sink Across From Three (3) Well Sink	20840100-062KF	11/30/2022	ND
Kitchen - Three (3) Well Sink - Left One	20840100-063KF	11/30/2022	5.62
Kitchen - Three (3) Well Sink - Right One	20840100-064KF	11/30/2022	14.7

Kitchen - Wall Mounted Hand Spray Hose - Above Three (3)	20840100-065KF	11/30/2022	185
Kitchen - Food Prep Sink Nearest Hot Bar Station	20840100-066KF	11/30/2022	9.93
Hose Bib - East Side Of Dumpster Corral	20840100-067OS	11/30/2022	47.4
Kitchen - Hand Sprayer attached to three (3) well sink	20840100-070KF	11/30/2022	4.6
Modular Small Hand Sink - West Side	20840102-068CF	11/30/2022	4.99
Modular Restroom Sink - West Side	20840102-069BF	11/30/2022	2.6
Modular Small Hand Sink - East Side	20840102-071CF	---	No Sample
Modular Restroom Sink - East Side	20840102-072BF	---	No Sample

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			
Hose Bib - East Side Of Dumpster Corral	20840100-067OS	1/19/2023	ND
Kitchen - Wall Mounted Hand Spray Hose - Above Three (3) Well Sink	20840100-065KF	12/12/2022	Removed from service

ND = Non Detect - Lead level is below the set detection limits of X ppb