

Water Testing Results - Elmira High School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Main Office Workroom Sink	20840400-001SF	2/28/2023	ND
Main Office Womens Restroom Faucet	20840400-002BF	2/28/2023	ND
Main Office Mens Restroom Faucet	20840400-003BF	2/28/2023	ND
Health Room Sink	20840400-004NS	2/28/2023	3.31
Health Room Ice Machine	20840400-005IM	2/28/2023	ND
Health Room Restroom	20840400-006BF	2/28/2023	ND
Room 3 Classroom Sink L-R , Far Left	20840400-007CF	2/28/2023	3.72
Room 3 Classroom Sink L-R	20840400-008CF	2/28/2023	4.33
Room 3, Left to Right	20840400-009CF	2/28/2023	3.93
Room 3, Left to Right	20840400-010CF	2/28/2023	4.6
Room 3, Left to Right	20840400-011CF	2/28/2023	2.13
Room 3, Left to Right, Far Right	20840400-012CF	2/28/2023	4.85
H.O.F. Restroom - Women's, Far Left	20840400-028BF	2/28/2023	ND
H.O.F. Restroom - Women's	20840400-029BF	2/28/2023	ND
H.O.F. Restroom - Women's	20840400-030BF	2/28/2023	ND
H.O.F. Restroom - Women's	20840400-031BF	2/28/2023	ND
H.O.F. Restroom - Women's	20840400-032BF	2/28/2023	2.76
H.O.F. Family Restroom	20840400-033BF	2/28/2023	3.67
H.O.F Restroom - Men's - Left	20840400-034BF	2/28/2023	ND
H.O.F. Restroom - Men's - Middle	20840400-035BF	2/28/2023	ND
H.O.F Restroom - Men's - Right	20840400-036BF	2/28/2023	ND
H.O.F. Atrium Water Bottle Station	20840400-037WB	2/28/2023	ND
H.O.F. Atrium Drinking Fountain	20840400-038DW	No Water Supply	---
Concessions Sink - Left	20840400-039KF	2/28/2023	2.53
Concessions Sink - Right	20840400-040KF	2/28/2023	2.98
Concessions Ice Machine	20840400-041IM	No Water Supply	---
Staff Lounge Faucet	20840400-042SF	2/28/2023	ND
Staff Lounge Instant Hot Water	20840400-043SF	2/28/2023	ND
Staff Restroom - Womens	20840400-044BF	2/28/2023	ND

Staff Restroom - Unisex	20840400-045BF	2/28/2023	ND
Coffee Cart Sink	20840400-046SF	2/28/2023	5.06
Senior Hallway Drinking Fountain - Left	20840400-047DW	2/28/2023	ND
Senior Hallway Drinking Fountain - Right	20840400-048DW	2/28/2023	ND
Room 7 Classroom Sink	20840400-049CF	2/28/2023	5.29
LCC Office Sink	20840400-050CF	2/28/2023	ND
LCC Office Instant Hot Water	20840400-051CF	2/28/2023	ND
LCC Men's Restroom Sink - Left	20840400-052BF	2/28/2023	ND
LCC Men's Restroom Sink - Right	20840400-053BF	2/28/2023	ND
LCC Women's Restroom Sink - Left	20840400-054BF	2/28/2023	ND
LCC Women's Restroom Sink - Right	20840400-055BF	2/28/2023	ND
Room 13 Classroom Sink	20840400-056CF	2/28/2023	2.69
Theater Dressing Room Sink	20840400-057CF	2/28/2023	7.63
Room 23 Classroom Sink	20840400-058CF	2/28/2023	ND
Track Outside Spigot	20840400-059OS	2/28/2023	22
Room 30 Classroom Sink	20840402-001CF	2/28/2023	ND
Room 32 Classroom Drinking Fountain	20840402-002DW	2/28/2023	ND
Cafeteria Drinking Fountain - Left	20840403-001DW	No Water Supply	----
Cafeteria Drinking Fountain - Right	20840403-002DW	3/2/2023	ND
Cafeteria Restroom - Women - Left	20840403-003BF	3/2/2023	ND
Cafeteria Restroom - Women - Right	20840403-004BF	3/2/2023	ND
Cafeteria Restroom - Men - Left	20840403-005BF	3/2/2023	2.02
Cafeteria Restroom - Men - Right	20840403-006BF	3/2/2023	ND
Kitchen Sink - Cafe Area - Side Main Kitchen	20840403-007KF	3/2/2023	2.43
Kitchen Restroom Sink	20840403-008BF	3/2/2023	ND
Kitchen Hand Sink Across From Office	20840403-009KF	3/2/2023	ND
Kitchen Prep Sink - Near Back Door	20840403-010KF	3/2/2023	ND
Kitchen Ice Maker	20840403-011IM	3/2/2023	ND
Kitchen Three Well Sink	20840403-012KF	3/2/2023	3.42
Kitchen Dish Sprayer	20840403-013KF	3/2/2023	ND
Kitchen Hand Sink - Near Coolers	20840403-014KF	3/2/2023	ND
Kitchen Prep Sink - Near Ovens	20840403-015KF	3/2/2023	ND
Kitchen Steam Kettle - Left	20840403-016KF	3/2/2023	6.07
Kitchen Steam Kettle - Middle	20840403-017KF	3/2/2023	6.31
Kitchen Steam Kettle - Right	20840403-018KF	3/2/2023	9.95

Room 33 Classroom Sink - In Office	20840404-001CF	2/28/2023	4.22
Athletic Field Restroom Sink - Men- Left	20840404-002BF	2/28/2023	10.3
Athletic Field Restroom Sink - Men-Right	20840404-003BF	2/28/2023	9.26
Athletic Field Restroom Sink - women- left	20840404-004BF	2/28/2023	23.6
Athletic Field Restroom Sink - Women - Right	20840404-005BF	2/28/2023	ND
Room 35 - Classroom Sink	20840405-001CF	2/28/2023	13.2
Room 35 - Classroom Drinking Fountain	20840405-002DW	2/28/2023	46.2
Main Hallway Drinking Cooler	20840405-003WC	2/28/2023	ND
Restroom Sink	20840405-004BF	2/28/2023	5.95
Storgae Room Outside Women's Locker Rm.	20840406-001CF	2/28/2023	34.8
Women's Locker Restroom Sink - Left	20840406-002BF	2/28/2023	ND
Women's Locker Restroom Sink - Right	20840406-003BF	2/28/2023	ND
Women's Locker Room Drinking Fountain	20840406-004DW	2/28/2023	3.51
Main Gym Training Room Sink	20840406-005CF	2/28/2023	ND
Main Gym Training Room Ice Maker	20840406-006IM	2/28/2023	ND
Main Gym Hallway Women's Sink - Left	20840406-007BF	2/28/2023	6.47
Main Gym Hallway Women's Sink - Right	20840406-008BF	2/28/2023	ND
Main Gym Hallway ADA Drinking Fountain	20840406-009DW	2/28/2023	ND
Main Gym Hallway Drinking Fountain	20840406-010DW	2/28/2023	ND
Boy's Locker Room Water Cooler	20840407-001WC	2/28/2023	ND
Boy's Locker Room Restroom Sink	20840407-002BF	2/28/2023	ND
Boy's Locker Room P.E. Teacher Rest Room	20840407-003BF	2/28/2023	ND
Auxillary Gym Water Bottle Station	20840407-004WB	2/28/2023	ND
Auxillary Gym Drinking Fountain	20840407-005DW	No Water Supply	----
Center Quad Bathroom - Mens - Left	20840408-001BF	2/28/2023	8.64
Center Quad Bathroom - Mens - Right	20840408-002BF	2/28/2023	7.41
Center Quad Restroom - Womens - Left	20840408-003BF	No Water Supply	---
Center Quad Restroom - Womens - Right	20840408-004BF	2/28/2023	4.53
Football Consession Sink	20840412-001KF	2/28/2023	26
Football Consession Outside Faucet	20840412-002OS	2/28/2023	61
Baseball Home Dugout Outside Spigot	20840414-001OS	2/28/2023	21.4
Softball Home Dugout Drinking Fountain	20840415-001DW	2/28/2023	34.1
Softball Home Dugout Outside Spigot	20840415-002OS	2/28/2023	207
Softball Visitor Dugout Drinking Fountain	20840415-002DW	2/28/2023	66.7

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			
Track Outside Spigot	20840400-059OS	4/26/2023	11.2
Athletic Field Restroom Sink - women- left	20840404-004BF	4/26/2023	8.13
Room 35 - Classroom Sink	20840405-001CF	4/26/2023	10.07
Room 35 - Classroom Drinking Fountain	20840405-002DW	4/26/2023	8.32
Storgae Room Outside Women's Locker Rm.	20840406-001CF	4/26/2023	9.09
Football Consession Sink	20840412-001KF	4/26/2023	7.78
Football Consession Outside Faucet	20840412-002OS	4/26/2023	ND
Baseball Home Dugout Outside Spigot	20840414-001OS	4/26/2023	13.2
Softball Home Dugout Drinking Fountain	20840415-001DW	Removed Fixture	
Softball Home Dugout Outside Spigot	20840415-002OS	4/26/2023	10
Softball Visitor Dugout Drinking Fountain	20840415-002DW	Removed Fixture	

ND = Non Detect - Lead level is below the set detection limits of X ppb