

Water Testing Results - Fern Ridge Middle School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Front Office Health Room Restroom	20840200-001BF	2/1/2023	ND
Left Drinking Fountain Outside Main Office	20840200-002DW	2/1/2023	ND
Right Drinking Fountain Outside Main Office	20840200-003DW	2/1/2023	ND
Bottle Fill Station Outside Main Office	20840200-004WB	2/1/2023	ND
Drinking Fountain Between Rms. 14 and 15	20840200-005WC	2/1/2023	ND
Staff Lounge Kitchen Sink	20840200-006SF	2/1/2023	ND
Staff Lounge Instant How Water	20840200-007SF	2/1/2023	ND
Staff Lounge Sink Sprayer	20840200-008SF	2/1/2023	2.53
Staff Lounge Restroom - Left	20840200-009BF	2/1/2023	ND
Staff Lounge Restroom - Right	20840200-010BF	2/1/2023	ND
Main Hallway Girls Bathroom - Left	20840200-011BF	2/1/2023	ND
Main Hallway Girls Bathroom - Middle	20840200-012BF	2/1/2023	ND
Main Hallway Girls Bathroom - Right	20840200-013BF	2/1/2023	ND
Main Hallway Boys Restroom - Left	20840200-014BF	2/1/2023	ND
Main Hallway Boys Restroom - Middle	20840200-015BF	--	--
Main Hallway Boys Restroom - Right	20840200-016BF	2/1/2023	ND
Drinking Fountain Between Rms. 16 and 17	20840200-017WC	2/1/2023	ND
Bottle Fill Station Between Rms. 16 and 17	20840200-018WB	2/1/2023	2.21
Room 20 - Classroom Sink	20840200-019CF	2/1/2023	3.19
Room 20 - Classroom Drinking Fountain	20840200-020DW	2/1/2023	21.3
Room 22 - West Wall Faucet - Left	20840200-021CF	2/1/2023	ND
Room 22 - West Wall Faucet - Middle	20840200-022CF	2/1/2023	ND
Room 22 - West Wall Faucet - Right	20840200-023CF	2/1/2023	ND
Room 22 - East Wall Faucet - Left	20840200-024CF	2/1/2023	2.23
Room 22 - East Wall Faucet - Middle	20840200-025CF	--	--
Room 22 - East Wall Faucet - Right	20840200-026CF	2/1/2023	ND
Room 22 - South Wall Faucet	20840200-027CF	2/1/2023	ND
Cafeteria Girls Restroom Faucet - Left	20840200-028BF	2/1/2023	ND
Cafeteria Girls Restroom Faucet - Right	20840200-029BF	2/1/2023	ND

Cafeteria Drinking Fountain	20840200-030WC	2/1/2023	ND
Cafeteria Boys Restroom Faucet - Left	20840200-031BF	2/1/2023	ND
Cafeteria Boys Restroom Faucet - Right	20840200-032BF	2/1/2023	ND
Room 23 - Classroom Faucet - Left	20840200-033CF	2/1/2023	ND
Room 23 - Classroom Faucet - Right	20840200-034CF	2/1/2023	ND
Room 24 - East Wall Faucet	20840200-035CF	--	--
Room 24 - West Wall Faucet	20840200-036CF	--	--
Room 25 - Utility Sink	20840200-037CF	2/1/2023	7.36
Room 27 - Classroom Sink	20840200-038CF	2/1/2023	2.4
Room 27 - Classroom Drinking Fountain	20840200-039DW	2/1/2023	18.8
Room 29 - Classroom Drinking Fountain	20840200-040DW	2/1/2023	ND
Room 29 - Restroom Faucet - Left	20840200-041BF	2/1/2023	ND
Room 29 - Restroom Faucet - Right	20840200-042BF	2/1/2023	ND
Room 30 - Classroom Drinking Fountain	20840200-043DW	2/1/2023	ND
Room 30 - Restroom Faucet - Left	20840200-044BF	2/1/2023	ND
Room 30 - Restroom Faucet - Right	20840200-045BF	2/1/2023	ND
Kitchen Small Handwash Sink	20840200-046KF	2/1/2023	ND
Kitchen Three Well Sink	20840200-047KF	2/1/2023	ND
Kitchen Sprayer Sink	20840200-048KF	2/1/2023	ND

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			
Room 20 - Classroom Drinking Fountain	20840200-020DW	4/26/2023	3.14
Room 27 - Classroom Drinking Fountain	20840200-039DW	4/26/2023	2.52

ND = Non Detect - Lead level is below the set detection limits of X ppb